

Leslie Road Condition Survey.

Please see photos of condition survey for Leslie Road carried out with Steve Sykes from Highways on 9th September 2009

PHOTOS

4 to 10 =Leslie Road from play area towards Raymond Road



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10

11 to 13 = Entrance of Doncaster Road onto Raymond Road



Photo 11



Photo 12



Photo 13

14 to 17 =outside house number 11, 13, 15 Raymond Road



Photo 14



Photo 15



Photo 16



Photo 17

18 = outside 17 Raymond Road



Photo 18

19 = opposite 31 Raymond Road



Photo 19

20/21 = opposite 37 Raymond Road



Photo 20



Photo 21

22 = junction Reginald/Raymond Road



Photo 22

23 = opposite 45 Reginald Road



Photo 23

24 = outside 47 Reginald Road



Photo 24

25/26 = junction Birch/Reginald Road



Photo 25



Photo 26

27 = opposite 63 Reginald Road



Photo 27

28/29 = opposite 75 Reginald Road



Photo 28



Photo 29

30/31 = junction of Laurel/Reginald/Leslie Road



Photo 30



Photo 31

32 = outside play area



Photo 32

33/34 = Leslie Road outside play area



Photo 33



Photo 34

35 = Footpath side of play area



Photo 35