**Shopfront under construction;**
Additional steel was installed to allow the suspended glazing fins over the entrance
once the glazing was installed, it was discovered the shopfitters could not gain sufficient access to enable them to board and decorate the outer face of the steelwork.







**Completed Shopfront;**
Several option were considered to best finish the area over the store entrance.
Vinyl including perforated was installed for review by the retail shopfitting team.
To give a premium look, it was decided that gloss acrylic panels should be fitted to try and match in with the gloss 'back painted glass' along the top of the facade.

