


10, Worsbrough Village, Barnsley, S70 5LW



Block Plan shows area bounded by: 434962.31, 402641.51 435052.31, 402731.51 (at a scale of 1:500) The representation of a road, track or path is no evidence of a right of way. The representation of features as lines is no evidence of a property boundary.

Produced on 17th May 2016 from the Ordnance Survey National Geographic Database and incorporating surveyed revision available at this date. Reproduction in whole or part is prohibited without the prior permission of Ordnance Survey. © Crown copyright 2016. Supplied by buyaplan.co.uk a licensed Ordnance Survey partner (100053143). Unique plan reference: #00125896-F076C9

Ordnance Survey and the OS Symbol are registered trademarks of Ordnance Survey, the national mapping agency of Great Britain. Buy A Plan logo, pdf design and the buyaplan.co.uk website are Copyright © Pass Inc Ltd 2016



Photograph of Wood Worm Destroyed Ceiling Joists - Inspection of the wood shows it is easily removed leaving little of the original wood.

It is proposed that these joists are replaced with new oak beams. This will be necessary as they will also need to form the trimmers for the new staircase.