

Appendix C







EXISTING BASEMENT FLOOR PLAN



EXISTING GROUND FLOOR PLAN




EXISTING FIRST FLOOR PLAN




EXISTING SECOND FLOOR PLAN




EXISTING NORTH ELEVATION
(SACKVILLE STREET)



EXISTING EAST ELEVATION
(FITZWILLIAM STREET)




EXISTING SOUTH ELEVATION
(COALBY WALK)



EXISTING WEST ELEVATION

Existing Property





Proposed Development

Appendix D





View South along the east boundary of site



Evidence of cracking on the exterior walls





Overgrown courtyard in the south of the site, viewed from Fitzwilliam Street





Exterior western wall of Fitzwilliam Inn, viewed from grassed area in north of site

