


RAILWAY
dense overgrown area
unable to survey
rough grass
area of bushes
unsurfaced track
brick building
brick building
brick and cladded building
tarmac
tarmac car park
shrubs
BLEACHCROFT WAY
TARMAC
TREE CANOPY
STREAM
TOP OF BANK
BOTTOM OF BANK
disused canal
STONE RETAINING WALL
POST & WIRE MESH FENCE
BRICK WALL
EXISTING BUILDING